





L90
Left 90 degree turn



R90
Right 90 degree turn



T36
Turn 360 degrees



STP
Stop for 2 seconds



SPD
Speed up for 2 seconds